



## Work continues on Performing Arts Center

While it doesn't look like much progress is taking place on the outside, there is a ton of activity taking place outside of view. Crews are busily at work trying to finish exterior work. Next week's work calls for the installation of the roof to be placed over the lower levels of the building so crews can continue to work on the mechanical, storage, vocal music and band areas over the winter. Pictured at right, two cranes are currently providing block and mortar to 27 masons laying block. Executive Director of Operations **Phil Thom** said the process is moving along quickly as the masons lay 4-feet of block at a time and then move to work on another 4-foot section while the mortar and grout are placed on the block they just installed.

